

# 2015 Piper Malibu Matrix



Contact: Bob Tait

Ph: 908-248-2628 | Email: [bob@btaviation.com](mailto:bob@btaviation.com)









## 2015 Piper Malibu Matrix

**Total Time:** 431.0 Hours

**Engine:** 431.0 Hours

**Propeller:** 431.0 Hours

**Engine:**

Lycoming TIO-540-AE2A

**Propeller:**

Hartzell

**Maintenance:**

On standard Part 91 annual inspection cycle. Last annual September 2019.

All AD and SB complied with.

New T.I.T probe and calibration September 2019

**Avionics:**

Garmin G1000 3 panel system (Pilot/Co-Pilot Primary Flight Displays and larger center Multi-Function Display)

GPS WAAS (Garmin G1000)

All electric backup Airspeed, Attitude, and Altitude instruments (No vacuum system)

ADS-B In/Out (G1000)

Garmin GFC700 autopilot with altitude select

**Features:**

120v inverter with access plugs in Pilot area and in Passenger area. (Factory equipment)

Relief funnel (Factory equipment)

**Interior:**

6 seat black leather interior (Pilot, Co-Pilot, and 4 passengers in club seating)

**Exterior:**

Original factory paint; excellent condition. (Matterhorn White with Sable and Red trim)



Contact: Bob Tait

Ph: 908-248-2628 | Email: [bob@btaviation.com](mailto:bob@btaviation.com)